

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/23/2020

Submitted Date:

07/24/2020

Document Number:

701001022**FIELD INSPECTION FORM**Loc ID 302969 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone | Email                           | Comment |
|---------------|-------|---------------------------------|---------|
| Beard, Alyssa |       | regulatory@foundationenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 252183      | WELL | PR     | 06/01/2015  | GW         | 125-06051 | NEW A-1       | PR          |

**General Comment:**Routine Inspection

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Dirt road through pasture |       |  |
| Corrective Action  | L                         | Date: |  |

Overall Good: ☒

|                      |   |       |  |
|----------------------|---|-------|--|
| <b>Signs/Marker:</b> |   |       |  |
| Type                 | WELLHEAD  |       |  |
| Comment:             | Lease sign by wellhead                                |       |  |
| Corrective Action:   |   | Date: |  |
| Type                 | OTHER   |       |  |
| Comment:             | Lease sign for associated wells mounted to meter shed |       |  |
| Corrective Action:   |   | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |   |       |  |
|--------------------|---|-------|--|
| <b>Fencing/:</b>   |   |       |  |
| Type               | WELLHEAD  |       |  |
| Comment:           | Metal panels around wellhead, VGS and meter sheds |       |  |
| Corrective Action: |   | Date: |  |

|                           |  |       |                 |
|---------------------------|--|-------|-----------------|
| <b>Equipment:</b>         |  |       | corrective date |
| Type: Gas Meter Run       | # 5  |       |                 |
| Comment:                  | Shared meter run for New A-1, Rose 11-17, Shay 6-17, 10-17 & 12-17 |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Vertical Separator  | # 5  |       |                 |
| Comment:                  | 5-Vertical gas separators 50% buried by meter sheds                |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Ancillary equipment | # 2  |       |                 |
| Comment:                  | Telemetry equipment for each meter shed                            |       |                 |
| Corrective Action:        |  | Date: |                 |

|                 |  |  |  |
|-----------------|--|--|--|
| <b>Venting:</b> |  |  |  |
| Yes/No          |  |  |  |
| Comment:        |  |  |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |  |       |      |             |           |         |    |               |    |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 252183   | Type: | WELL | API Number: | 125-06051 | Status: | PR | Insp. Status: | PR |
| Producing Well       |  |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing production. Central meter run for (Rose 11-17, New A-1, Shay 6-17, 10-17, 12-17) |       |      |             |           |         |    |               |    |
| Corrective Action:   |  |       |      |             |           |         |    | Date:         |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**    ☒ NO SURFACE INDICATION OF PIT
**Attached Documents**
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description    | URL   |
|--------------|----------------|---|
| 701001037    | location photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5211617">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5211617</a> |