

Inspection Photos

Location Name: LARAMIE ENERGY LLC Wagon Track Federal /12-14 Pad

Location ID: 312656



Photo #1622 from entrance to location



Photo #0883 from inspection # 699800826 conducted on 3/31/20.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Wagon Track Federal /12-14 Pad

Location ID: 312656



Photo #1030 from inspection #699800974 conducted on 4/23/20.



Photo #1624 Secondary containment berm has eroded.