

Inspection Photos

Location Name: LARAMIE ENERGY LLC Wagon Track Federal /12-16 Pad

Location ID: 312657



Photo #1625 from entrance to location



Photo #1626 from entrance to location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Wagon Track Federal /12-16 Pad

Location ID: 312657



Photo #0879 from inspection # 699800820 conducted on 3/31/20.



Photo #1032 from inspection #699800976 conducted on 4/23/20.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Wagon Track Federal /12-16 Pad

Location ID: 312657



Photo #1627 Secondary containment berm has eroded.