

Inspection Photos
Location Name: Dowdell 1
Location ID: 324668



Photo 1. Overview of location taken facing southwest.



Photo 2. Are separators in use?



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dowdell 1
Location ID: 324668



Photo 3. Tank stored on location with no labels or secondary containment.



Photo 4. Tank stored on location with no labels or secondary containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources