

Inspection Photos

API: 055-06169

Operator: PETROGLYPH OPERATING CO INC

Inspection Date: 7/22/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06169 | Date: 7/22/2020

Inspection Photos



Photo 1. Facing southeast along the access road which remains per approved variance..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06169 | Date: 7/22/2020

Inspection Photos



Photo 2. Facing south along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06169 | Date: 7/22/2020

Inspection Photos



Photo 3. Facing south along the further along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06169 | Date: 7/22/2020

Inspection Photos



Photo 4. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06169 | Date: 7/22/2020

Inspection Photos



Photo 5. There is a 20 ft. black plastic pipe that remains at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06169 | Date: 7/22/2020

Inspection Photos



Photo 6. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06169 | Date: 7/22/2020

Inspection Photos



Photo 7. There is another black plastic pipe at the center of the location which is buried into the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06169 | Date: 7/22/2020

Inspection Photos



Photo 8. Facing southwest toward the southern portion of the location. The desirable vegetation has fully established in this portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06169 | Date: 7/22/2020

Inspection Photos



Photo 9. There is a metal pipe that remains at the southeast side of the location.



Inspection Photos



Photo 10. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06169 | Date: 7/22/2020

Inspection Photos



Photo 11. Facing south toward the surrounding undisturbed rangeland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06169 | Date: 7/22/2020