

# Inspection Photos

API: 055-06261

Operator: PETROGLYPH OPERATING CO INC

Inspection Date: 7/27/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06261 | Date: 7/27/2020

## Inspection Photos



**Photo 1.** Facing northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06261 | Date: 7/27/2020



## Inspection Photos



**Photo 2.** Facing west toward the location. The desirable vegetation has uniformly established at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06261 | Date: 7/27/2020



## Inspection Photos



**Photo 3.** Facing northwest toward the location. The vegetation observed consisted of Blue grama, Sand dropseed, Western wheat, among other species.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06261 | Date: 7/27/2020



## Inspection Photos



**Photo 4.** Facing east at toward the cut slope which is stabilized with vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06261 | Date: 7/27/2020



## Inspection Photos



**Photo 5.** Facing southeast at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06261 | Date: 7/27/2020



## Inspection Photos



**Photo 6.** Facing southeast along the cut slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06261 | Date: 7/27/2020



## Inspection Photos



**Photo 7.** Facing southwest at the location from the top of the cut slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06261 | Date: 7/27/2020