Pit Status Evaluation Form

Pit Overview:

Pit Name: **Miller 1-23** **Facility ID:** **118392**

Current Status: Unknown **Status Date:** 9/23/1999

Current Operator: HIBBERT* ESTATE OF R E 39850

Updated Operator: THREE STATE WELL SERVICE INC 88005

Form 15 Pit Permit Doc #: 383537 **Permit Date:** 4/25/1983

Related Facilities: Well: 123-10327
Location: 407240

County: Weld

Township: 9N **Range:** 56W **Section:** 21 **QQ:** NENE

Original Latitude/ Longitude: 40.743576 / -103.633119

Updated Latitude/ Longitude: /

Basis for Location Change:

Pit Inspection/Information Request:

Field Inspection Date: **Document #:**

Pit Still Present in Field: No

Visible Surface Impacts: ☐ **Stressed Vegetation** ☐ **Surface Depression** ☐ **Stained Soil** ☐ **Other (see below)**

Inspection Notes:

Operator Required to Submit Form: NA **Due Date:**

Form Request Sent To: **Sent Date:**

Pit Status Evaluation:

Pit Status Review Documents:

- [x] **Form 15 Pit Permit – Doc #:** 383537 **Date:** 4/25/1983
- [x] **Field Inspection(s) – Doc #:** 383538 **Date:** 10/22/1984
  - **Doc #:** 383539 **Date:** 6/23/1986
  - **Doc #:** **Date:**
- [ ] **Form 27 Remediation Workplan – Project #:** **Date:**
- [ ] **Form 4 Sundry Notice – Doc #:** **Date:**
- [ ] **COGIS Document – Doc #:** **Date:**
- [ ] **Pit Inventory – Doc #:** **Date:**
- [ ] **Duplicate Record – Duplicate Pit(s) #:**
- [ ] **Aerial Photo Verification (photos attached)**
- [ ] **Other:**

Pit Status Determination

Updated Pit Status: Closed **Pit Status Date: 10/22/1991**

Timing of Pit Closure:

With Reclamation

Pit Status Review Summary:

Based on a records review and aerial imagery, the pit was reclaimed prior to 1997. Per 1997 regulations, pits closed prior to this date need only comply with surface reclamation standards. Well was plugged on 12/7/1990 and passed final reclamation inspection 10/22/1991. Pit status has been changed to Closed.