

Inspection Photos

Location Name: ELDRIDGE 25-01-#2

API#: 05-067-09566

INSP. #: 695102996



Colorado Oil & Gas Conservation Commission
37.08111, -107.99116, 1920.0m, 72°
2020/07/21 15:46:06



PHOTO 2: WELL SIGN

PHOTO 1: LOCATION

Inspection Photos
Location Name: ELDRIDGE 25-01-#2
API#: 05-067-09566
INSP. #: 695102996



**PHOTO 3: UNUSED EQUIPMENT STORED ON LOCATION.
REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.f.
CA DATE 10-21-20**

**PHOTO 4: TRASH ON LOCATION. REMOVE ALL TRASH ON
AND AROUND LOCATION COMPLY WITH RULE 603.f. CA DATE
10-21-20**

Inspection Photos

Location Name: ELDRIDGE 25-01-#2

API#: 05-067-09566

INSP. #: 695102996




PHOTO 5: NOXIOUS WEEDS AROUND THE EDGES OF LOCATION. REMOVE WEEDS COMPLY WITH RULE 603.f. CA DATE 10-21-20

PHOTO 6: ANOTHER IMAGE OF NOXIOUS WEEDS AROUND LOCATION. REMOVE WEEDS COMPLY WITH RULE 603.f. CA DATE 10-21-20

Inspection Photos
Location Name: ELDRIDGE 25-01-#2
API#: 05-067-09566
INSP. #: 695102996



Colorado Oil & Gas Conservation Commission
 37.08205, -107.98992, 1988.0m, 73°
 2020/07/21 15:50:49



Colorado Oil & Gas Conservation Commission
 37.08225, -107.99006, 1986.0m, 213°
 2020/07/21 16:15:50

PHOTO 7: SIGN BROKE AND LYING ON THE GROUND ALSO THERE IS NO TANK CAPASITY POSTED ON OR NEAR PRODUCED WATER TANK. POST SIGN IN ACCORDANCE WITH RULE 210.b. CA DATE 10-21-20.

PHOTO 8: CAL. REPORT SHOWS LAST CALIBRATION WAS 2005. Provide calibration records or calibrate meter as required by Rule 329. CA DATE 8-21-20.