

Inspection Photos
Location Name: LE PLATT 1
API#: 05-067-06743
INSP. #: 695103001



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: LE PLATT 1
API#: 05-067-06743
INSP. #: 695103001



PHOTO 3: UNUSED EQUIPMENT STORED NEAR TELEMETRY EQUIPMENT FENCE (TARMPS AND PALLETS). REMOVE ALL UNUSED EQUIPEMNT PER RULE 603.f. CA DATE 10-22-20



PHOTO 4: UNUSED EQUIPMENT STORED NEAR TELEMETRY EQUIPMENT FENCE (PORTABLE FENCE PANELS). REMOVE ALL UNUSED EQUIPEMNT PER RULE 603.f. CA DATE 10-22-20

Inspection Photos
Location Name: LE PLATT 1
API#: 05-067-06743
INSP. #: 695103001



Colorado Oil & Gas Conservation Commission
37.23321, -107.6068, 2089.0m, 202°
2020/07/22 11:08:59

**PHOTO 5: NOXIOUS WEEDS AND OTHER VEGETATION
OVERGROWTH AROUND TELEMETRY EQUIPMENT. REMOVE
NOXIOUS WEEDS AND MAINTAIN ALL OTHER VEGETATION
PER RULE 603.f. CA DATE 8-4-20.**