

Inspection Photos
Location Name: LA PLATT B-1
API#: 05-067-08931
INSP. #: 695103003



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



Inspection Photos
Location Name: LA PLATT B-1
API#: 05-067-08931
INSP. #: 695103003



PHOTO 3: Natural gas powered engine exhaust is staining soil/gravel around area of muffler.

Remove stained soil/gravel and dispose. Comply with Rule 1102.f.(2) for best self inspection, maintenance and housekeeping to prevent breakdown or failure of BMP's. CA DATE IS ORIGINAL FROM PREVIOUS INSPECTION DOC#687904818



PHOTO 4: Approx 2' x 2' area of stained soil/gravel around base of wellhead. Clean-up and dispose of stained soil/gravel per Rule 1102.f.(2) and Rule 907.e.
CA DATE IS ORIGINAL FROM PREVIOUS INSPECTION DOC#687904818

Inspection Photos
Location Name: LA PLATT B-1
API#: 05-067-08931
INSP. #: 695103003



**PHOTO 5: NOZIOUS WEEDS ON NORTH EDGE OF LOCATION NEAR
GAS METER RUN FENCING. REMOVE NOXIOUS WEEDS COMPLY
WITH RULE 1003.f. CA DATE 7-29-20.**