

Inspection Photos
Location Name: STATE CD 1 & 3
API#: 05-067-07852
INSP. #: 695103007



Colorado Oil & Gas Conservation Commission
37.18857, -107.63161, 2083.0m, 152°
2020/07/22 14:06:19



Colorado Oil & Gas Conservation Commission
37.18858, -107.63161, 2080.0m, 144°
2020/07/22 14:06:30

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: STATE CD 1 & 3
API#: 05-067-07852
INSP. #: 695103007



PHOTO 3: Canada Thistle growing at entrance to location and in perimeter of the interim reclamation area. Remove weeds and manage to prevent spread to comply with Rule 1003.f. CA DATE 7-29-20.

PHOTO 4: ANOTHER IMAGE OF CANADA THISTLE.

Inspection Photos
Location Name: STATE CD 1 & 3
API#: 05-067-07852
INSP. #: 695103007



PHOTO 5: UNUSED EQUIPMENT STORED ON LOCATION APPEARS TO BE DUMPTRUCK NOT RELATED TO OPERATOR OR OIL & GAS OPERATION. REMOVE UNUSED EQUIPMENT PER RULE 603.f. CA DATE 10-22-20.

PHOTO 6: PHOTO 4: Approx 2' x 2' area of stained soil/gravel around base of STATE CD 1 wellhead. Clean-up and dispose of stained soil/gravel per Rule 1102.f.(2) and Rule 907.e. CA DATE 8-12-20.

Inspection Photos
Location Name: STATE CD 1 & 3
API#: 05-067-07852
INSP. #: 695103007



Colorado Oil & Gas Conservation Commission
37.18821, -107.63142, 2073.0m, 24°
2020/07/22 14:10:12



Colorado Oil & Gas Conservation Commission
37.18797, -107.63146, 2070.0m, 147°
2020/07/22 14:11:12

PHOTO 7: Approx 2' x 2' area of stained soil/gravel around base of STATE CD 3 wellhead. Clean-up and dispose of stained soil/gravel per Rule 1102.f.(2) and Rule 907.e. CA DATE 8-12-20.

PHOTO 8: UNUSED EQUIPMENT (STAKES FOR WADDLES ARE LEFT ON INTERIM RECLAMATION AREA AROUND LOCATION). REMOVE UNUSED EQUIPMENT PER RULE 603.f. CA DATE 10-22-20.

Inspection Photos
Location Name: STATE CD 1 & 3
API#: 05-067-07852
INSP. #: 695103007



PHOTO 9: UNOTHER IMAGE OF CA FROM PHOTO 8.

PHOTO 10: TRASH INSIDE TANK BATTERY FENCING AND AROUND SOUTH SIDE OF LOCATION APPEARS TO BE PIECES OF WADDLES MESH NOT DISCARDED WHEN WADDLES WERE REMOVED. PICK UP ALL TRASH ON AND AROUND LOCATION PER RULE 603.f. CA DATE 10-22-20

Inspection Photos
Location Name: STATE CD 1 & 3
API#: 05-067-07852
INSP. #: 695103007



PHOTO 9: UNOTHER IMAGE OF CA FROM PHOTO 10.