

Inspection Photos  
Location Name: BUSH FEDERAL 2  
API#: 05-067-08663  
INSP. #: 695103018



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



Inspection Photos  
Location Name: BUSH FEDERAL 2  
API#: 05-067-08663  
INSP. #: 695103018



**PHOTO 3: MATURE FLOWERING NOXIOUS WEEDS ALL  
AROUND LOCATION AND ON INTERIM RECLAMATION AREA.  
CONTROL WEEDS CA DATE 7-27-20.**



**PHOTO 4: ANOTHER PHOTO OF MATURE NOXIOUS WEEDS  
FROM PHOTO 3.**



Inspection Photos  
Location Name: BUSH FEDERAL 2  
API#: 05-067-08663  
INSP. #: 695103018



**PHOTO 5: PLACARD ON SEPARATOR IN CRACKING AND STARTING TO FALL OFF. PLACARD WITH NEED REPLACED SOON.**



**PHOTO 6: THERE ARE SEVERAL PIECES OF TRASH AROUND LOCATION. **POLICE LOCATION AND SUROUNDING AREA FOR ALL TRASH, COMPLY WITH RULE 603.f. CA DATE 10-23-20****

