

Inspection Photos
Location Name: HUBER HECHT 1-4
API#: 05-067-07554
INSP. #: 695103028



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: HUBER HECHT 1-4
API#: 05-067-07554
INSP. #: 695103028



PHOTO 5: UNUSED EQUIPMENT (4" PIPE LEANING AGAINST SOUND WALLS). REMOVE UNUSED EQUIPMENT PER RULE 603.f. CA DATE 10-23-20.

Inspection Photos

Location Name: HUBER HECHT 1-4

API#: 05-067-07554

INSP. #: 695103028



PHOTO 3: MATURE FLOWERING NOXIOUS WEEDS ALL AROUND LOCATION AND ON INTERIM RECLAMATION AREA.
CONTROL WEEDS CA DATE 7-27-20.

PHOTO 4: ANOTHER IMAGE OF NOXIOUS WEEDS. CANT SEE IN PHOTO BUT THISTLE HAVE MIGRATED ALL THE WAY OUT IN THE FIELD SOUTHEAST OF LOCATION.