

Inspection Photos
Location Name: Jolly Platts#1
Location ID: 319643



Photo#1 Production Tanks

Photo#2 (3) Vertical Separators/ECD

Inspection Photos
Location Name: Jolly Platts#1
Location ID: 319643



Photo#3 Wellhead and Pumpjack

Photo#4 Bullplug missing

Inspection Photos
Location Name: Jolly Platts#1
Location ID: 319643



Photo#5 Bullplug Missing

Photo#6 Parts lying by tank


Inspection Photos
Location Name: Jolly Platts#1
Location ID: 319643



Photo#7 Stained Soil

Photo#8 Stained Soil

Inspection Photos
Location Name: Jolly Platts#1
Location ID: 319643



Photo#9 Stained Soil



Photo#10 Produced Water Tank

Inspection Photos
Location Name: Jolly Platts#1
Location ID: 319643



Photo#11 Unused equipment

Photo#12 Unused equipment