

Inspection Photos
Location Name: Abbott Farms#1
Location ID: 320050



Photo#1 Production Tank and Produced Water Pit
Corrective Action: Weeds



Photo#2 Separator/**Corrective Action: Weeds**

Inspection Photos
Location Name: Abbott Farms#1
Location ID: 320050



Photo#3 **Corrective Action: Weeds**



Photo#4 Wellhead/**Corrective Action: Weeds**

Inspection Photos
Location Name: Abbott Farms#1
Location ID: 320050



Photo#5 Gas Meter/**Corrective Action: Weeds**