

Inspection Photos  
Location Name: May 32-6  
Location ID: 320057



Photo#1 Production Tank and Produced Water Tank

Weeds



Photo#2 Separator/ECD/Gas Meter

Weeds

Inspection Photos  
Location Name: May 32-6  
Location ID: 320057



**Photo#3 Corrective Action: Stained Soil**



**Photo#4 Corrective Action: Weeds**