

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2020

Submitted Date:

07/28/2020

Document Number:

701001058**FIELD INSPECTION FORM**

Loc ID 303007 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252258	WELL	PR	08/01/2019	GW	125-06127	ENGLE 1-5	PR

General Comment:

Routine Inspection

Location					
Lease Road:					
Type	Access				
comment:	Dirt road through pasture				
Corrective Action					Date:
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	TANK LABELS/PLACARDS				
Comment:	Metal sign by water tank				
Corrective Action:					Date:
Type	WELLHEAD				
Comment:	Lease sign by meter shed				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:					
Corrective Action:					Date: _____
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	LOCATION				
Comment:	Metal panels around metal shed, VGS and water tank				
Corrective Action:					Date:
Equipment:					
					corrective date
Type: Ancillary equipment	# 2				
Comment:	Telemetry equipment. Bellows meter for domestic use				
Corrective Action:					Date:
Type: Gas Meter Run	# 2				
Comment:	Shared meter run for Engel 1-5 and 42-5				
Corrective Action:					Date:
Type: Vertical Separator	# 3				
Comment:	2-Vertical gas separators 50% buried by meter shed 1-Vertical gas separator in metal shed				
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.911700,-102.207400

Comment:	Fiberglass water tank 50% buried	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	150bbbs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	252258	Type:	WELL	API Number:	125-06127	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Engel 1-5 and 42-5)								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT
Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701001073	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213497