



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Banta Ridge 16-19-1-103      API: 05-103-10311**  
**Inspection: 700402647**





39.95123, -108.99235, 6001.9ft, 27°  
07/29/2020 01:58:52 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Well.**

**Banta Ridge 16-19-1-103      API: 05-103-10311**  
**Inspection: 700402647**





39.95128, -108.99225, 5992.4ft, 2°  
07/29/2020 01:59:37 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Meter building & separator.**

**Banta Ridge 16-19-1-103     API: 05-103-10311**  
**Inspection: 700402647**





39.95095, -108.99214, 6004.1ft, 7°  
07/29/2020 02:00:23 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Tanks.**

**Banta Ridge 16-19-1-103     API: 05-103-10311**  
**Inspection: 700402647**