

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/29/2020

Submitted Date:

07/29/2020

Document Number:

696103409**FIELD INSPECTION FORM**Loc ID 310509 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293234	WELL	PA	02/03/2017	OW	123-26512	MCKENNEY 14-14	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
 Well(s): 1: Plugged & Abandoned | PA.
 Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (305974, 309725).
 (Well(s): 2: Temporarily Abandoned | TA).

Centralized Battery formerly served 2 Location IDs (306222, 310509).
 (Well(s): 2: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696103404 and/or Location ID #305974
 for Battery / Facility, Equipment info.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

0

Comment: [Plugged & Abandoned | PA.](#)
[Equipment now assigned to Location ID 305974.](#)Corrective Action: Date:

Type: Pig Station

0

Comment: [Plugged & Abandoned | PA.](#)
[Equipment removed.](#)Corrective Action: Date:

Type: Plunger Lift

0

Comment: [Plugged & Abandoned | PA.](#) ALL equipment removed.Corrective Action: Date:

Type: Horizontal Heated Separator

0

Comment: [Plugged & Abandoned | PA.](#)
[Equipment now assigned to Location ID 305974.](#)Corrective Action: Date: **Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

Inspected Facilities

Facility ID: 293234 Type: WELL API Number: 123-26512 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 07/29/2020 at approximately 15:10 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: MCKENNEY-66N64W /14SENE Location ID: 310509 Well Name: McKenney 14-14 API: 05-123-26512 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (305974, 309725). (Well(s): 2: Temporarily Abandoned TA).</p> <p>Centralized Battery formerly served 2 Location IDs (306222, 310509). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696103404 and/or Location ID #305974 for Battery / Facility, Equipment info.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Well appears to be cut / capped. Form 6 doc. #401238940 indicates plugging, cut/cap date: 02/03/2017. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	07/29/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103410	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213746