

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402456572

Date Received:

07/30/2020

Spill report taken by:

FISCHER, ALEX

Spill/Release Point ID:

477094

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC	Operator No: 10598	<b>Phone Numbers</b>
Address: 123 ROBERT S KERR AVE		Phone: (817) 3076869
City: OKLAHOMA CITY	State: OK	Mobile: ( )
Zip: 73102	Contact Person: Dylan Mair	Email: dmair@sandridgeenergy.com

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402433203

Initial Report Date: 06/29/2020 Date of Discovery: 06/26/2020 Spill Type: Recent Spill

#### Spill/Release Point Location:

QTRQTR NESE SEC 16 TWP 7N RNG 80W MERIDIAN 6

Latitude: 40.573457 Longitude: -106.381427

Municipality (if within municipal boundaries): N/A County: JACKSON

#### Reference Location:

Facility Type: TANK BATTERY

☐ Facility/Location ID No

Spill/Release Point Name: Pintail Battery

☐ Well API No. (Only if the reference facility is well) 05- -

☒ No Existing Facility or Location ID No.

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): >=100

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: 155 bbl produced water spilled in containment.

#### Land Use:

Current Land Use: NON-CROP LAND

Other(Specify):

Weather Condition: Sunny

Surface Owner: FEE

Other(Specify): Greg Ray

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

155 bbl produced water discovered inside containment on 6/26/2020 at 10:30 MST. Cleanup complete via vac truck at 3:32 MST. Water did not leave containment. Water was disposed of down the Pintail 2 SWD.

List Agencies and Other Parties Notified:

### OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
6/26/2020	Greg Ray	ggrayranch@gmail.com	-	
6/26/2020	Kent Crowder	kentcrowder47@gmail.com	-	

Was there a Grade 1 Gas Leak? Yes ☐ No ☒

If YES, enter the Document Number of the Grade 1 Gas Leak Report Form 44: \_\_\_\_\_

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: \_\_\_\_\_

Was there damage during excavation? Yes ☐ No ☒

If YES, was CO 811 notified prior to excavation? Yes ☐ No ☐

### REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: \_\_\_\_\_

### OPERATOR COMMENTS:

The remaining fluids & salt staining were removed as follows: The liner was scrubbed with push brooms & fresh water, then sucked out with a vac truck. Absorbent media was used to soak up any residual cleaning water, then scooped up and disposed of. Request closure to Spill 477094.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Dylan Mair

Title: Production Engineer Date: 07/30/2020 Email: dmair@sandridgeenergy.com

### COA Type

### Description

	Based on a review of the information provided, it appears that no further action is necessary at this time and COGCC approves the closure request. A Site Investigation and Remediation WorkPlan (Form 27) will be required if major modifications to the tank battery are made (ie. removing and replacing the secondary containment and liner) and when the tank battery is closed.
--	---

### Attachment Check List

#### Att Doc Num

#### Name

402456572	SPILL/RELEASE REPORT(SUPPLEMENTAL)
402456679	FORM 19 SUBMITTED

Total Attach: 2 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)