

## Inspection Photos

Location Name: Park Mountain #9026

Location ID: 316204

Inspection Date: July 20, 2020



Photo – Location sign.



Photo – Tank battery looking southwest.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Park Mountain #9026**  
**Location ID: 316204**  
**Inspection Date: July 20, 2020**



**Photo - Tank battery looking northeast**



**Photo - Northeast side of the tank battery earthen secondary containment structure.**



## Inspection Photos

Location Name: Park Mountain #9026

Location ID: 316204

Inspection Date: July 20, 2020



**Photo - Southwest side of the tank battery earthen secondary containment structure.**



**Photo - The first tank lid looking from the location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Park Mountain #9026**  
**Location ID: 316204**  
**Inspection Date: July 20, 2020**



**Photo - The second tank lid looking from the location (red circle).**



**Photo - Wellhead where the audible leak was discovered.**

