

Inspection Photos
Location Name: Wagner 18-12 M4
Location ID: 320416



Photo #1 Tanks.



Photo #2 Separator & Meter.

Inspection Photos
Location Name: Wagner 18-12 M4
Location ID: 320416



Photo #3 Well Head.



Photo #4 Stained soil in berm next to tanks.

Inspection Photos
Location Name: Wagner 18-12 M4
Location ID: 320416



Photo #5 Stained soil next to Crude tank.



Photo #6 stained soil next to produced water tank.

Inspection Photos
Location Name: Wagner 18-12 M4
Location ID: 320416



Photo #7 trash a stained soil behind Crude tank.



Photo #8 stained soil next to produced water tank.