

Inspection Photos
Location Name: Margaret Twombly B-1 tank battery
Location ID: 336316



Photo 1 TB sign



Photo 2 TB weeds growing inside berm

Inspection Photos

Location Name: Margaret Twombly B-1 tank battery

Location ID: 336316



Photo 3 stained soil by TB flow line



Photo 4 produced water

Inspection Photos

Location Name: Margaret Twombly B-1 tank battery

Location ID: 336316



Photo 5 weeds growing all around Horizontal Heated Separator



Photo 6 weeds growing around Horizontal Heated Separator

Inspection Photos

Location Name: Margaret Twombly B-1 tank battery

Location ID: 336316



Photo 7 weeds growing around manifold