

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402450042

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC	Operator No: 10110	Phone Numbers Phone: (720) 595-2132 Mobile: ()
Address: 1001 17TH STREET #2000		
City: DENVER	State: CO Zip: 80202	
Contact Person: Jason Davidson	Email: jdavidson@gwp.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 15435

Initial Form 27 Document #: 402372025

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: TANK BATTERY	Facility ID: 441861	API #:	County Name: WELD
Facility Name: Pierce Unit Central Tank Battery 441861		Latitude: 40.643635	Longitude: -104.756987
** correct Lat/Long if needed: Latitude: 40.643836		Longitude: -104.757313	
QtrQtr: SESE	Sec: 22	Twp: 8N	Range: 66W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications CL Most Sensitive Adjacent Land Use Agricultural

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Pierce Lateral in place 75 feet to the northwest. Rural residential development in place across US HWY 85, 1,000 feet to the east. Rural residential property in place 1,100 feet to the southwest

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | |
| <input checked="" type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	3 areas totaling 200' x 85'	Pothole and Hand Auger Investigations

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On 2/20/20, a triplex pump froze and the overflow alarm malfunctioned on two produced water tanks, resulting in the release of approximately 15 bbls of oil and 250 bbls of water. All but approximately 3 bbls were contained within the unlined, earthen bermed secondary containment. The entire release was contained on location. Between 2/20/20 and 2/21/20, hydrovac equipment was used to remove four loads of standing liquids and impacted roadbase from the release area. Between 2/21/20 and 2/22/20, a backhoe was used to excavate an additional 140 cubic yards of impacted roadbase and soil from the release area. The impacted material was manifested and hauled offsite for proper disposal. On 2/25/20, a pothole investigation was conducted using a hydrovac to determine vertical and horizontal extent of hydrocarbon-impacted soils at the Site. Thirty-two potholes were excavated in the release area to depths ranging from 12 inches to 48 inches below ground surface (bgs). Initial visual and olfactory observations and photoionization detector (PID) readings indicated the presence of potential hydrocarbon-impacts in the natural clay soil beneath the roadbase. Potential impacts were also observed in the flow path to the south and west of the southeast corner of the secondary containment where liquids had breached the earthen berm. Based on these findings, further investigation is needed to delineate the extent of potentially impacted soil at the Site. No soil samples were submitted for laboratory analysis during the pothole investigation and groundwater was not encountered.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

On 4/23/20, Fremont Environmental (Fremont) conducted a hand auger investigation to delineate the vertical and horizontal extent of hydrocarbon-impacted soil at the release area. Eleven soil borings were advanced across the Site to depths ranging from 4 feet to 7 feet bgs. Based on field observations, twenty characterization soil samples were collected for laboratory analysis of benzene, toluene, ethylbenzene, and total xylenes (BTEX), Total Petroleum Hydrocarbons (TPH)- Gasoline Range Organics (GRO) and TPH- Diesel Range Organics (DRO). Groundwater was not encountered during this investigation. Please refer to the attached Figures 2 and 3 for an illustration of the hand auger boring locations and soil analytical results.

Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 20

Number of soil samples exceeding 910-1 7

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 17000

NA / ND

-- Highest concentration of TPH (mg/kg) 8400

NA Highest concentration of SAR

BTEX > 910-1 Yes

Vertical Extent > 910-1 (in feet) 7

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) \

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 910-1

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☒ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) 140

Volume of liquid waste (barrels) 300

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Great Western proposes to conduct excavation activities to remediate the impacted source area soil. Impacted soils will be excavated and transported offsite for disposal at a licensed disposal facility. Confirmation soil samples will be collected from the walls and base of the excavation and analyzed for BTEX, TPH-GRO, and TPH-DRO. The number and location of soil samples shall be appropriate to confirm remediation. Please refer to the attached Figure 4 for an illustration of the estimated excavation areas. The proposed remediation activities are planned to be conducted within 45 days of approval of this Form 27.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Please refer to the Source Removal Summary above for an explanation of the remedial action plan.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

☐ Ex Situ

_____ Excavate and offsite disposal
_____ If Yes: Estimated Volume (Cubic Yards) _____
_____ Name of Licensed Disposal Facility or COGCC Facility ID # _____
_____ Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

☐ _____ Bioremediation (or enhanced bioremediation)
☐ _____ Chemical oxidation
☐ _____ Air sparge / Soil vapor extraction
☐ _____ Natural Attenuation
☐ _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during the pothole and hand auger investigations.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☒ Other Following Remediation Activities

Report Type: ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report

☒ Other Remediation Progress Report

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

None

Volume of E&P Waste (solid) in cubic yards 140

E&P waste (solid) description Hydrocarbon-impacted roadbase and soil

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: Waste Management's North Weld Landfill in Ault, CO

Volume of E&P Waste (liquid) in barrels 300

E&P waste (liquid) description Hydrocarbon-impacted roadbase and soil

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: Pawnee Waste Landfill in Grover, CO

REMEDATION COMPLETION REPORT

REMEDATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

Do all soils meet Table 910-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? _____

Does Groundwater meet Table 910-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

If necessary, the site will be reclaimed in accordance with COGCC 1000 series rules.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim?

☐ Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 02/20/2020

Actual Spill or Release date, if known. 02/20/2020

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 02/20/2020

Date of commencement of Site Investigation. 02/25/2020

Date of completion of Site Investigation. 04/23/2020

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jason Davidson

Title: Senior EHS Specialist

Submit Date: _____

Email: jdavidson@gwp.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

Remediation Project Number: 15435

COA Type

Description

--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

402450459	SOIL SAMPLE LOCATION MAP
402450460	OTHER
402457135	ANALYTICAL RESULTS

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

Environmental	Returned to Draft for Operator to include analytical reports	07/30/2020
---------------	--	------------

Total: 1 comment(s)