



**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | LOCATION |       |  |
| Comment:           | Barbwire |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

| Type                              |     |       | corrective date |
|-----------------------------------|-----|-------|-----------------|
| Type: Bird Protectors             | # 4 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type:                             | #   |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Emission Control Device     | # 2 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 2 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Gas Meter Run               | # 2 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |

| <b>Tanks and Berms:</b>   |          |                     |                     |             |                       |       |
|---|----------|---------------------|---------------------|-------------|-----------------------|-------|
| Contents  | #        | Capacity            | Type                | Tank ID     | SE GPS                |       |
| PRODUCED WATER  | 1        | OTHER               | PBV CONCRETE        |             |                       |       |
| Comment: <a href="#">Shares containment with crude oil tanks.</a> |          |                     |                     |             |                       |       |
| Corrective Action:  |          |                     |                     |             |                       | Date: |
| <b>Paint</b>  |          |                     |                     |             |                       |       |
| Condition   |          |                     |                     |             |                       |       |
| Other (Content)   |          |                     |                     |             |                       |       |
| Other (Capacity)  |          |                     |                     |             |                       |       |
| Other (Type)  |          |                     |                     |             |                       |       |
| <b>Berms</b>  |          |                     |                     |             |                       |       |
| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |       |
|   |          |                     |                     |             |                       |       |
| Comment:  |          |                     |                     |             |                       | Date: |
| Corrective Action:  |          |                     |                     |             |                       | Date: |
| Contents  | #        | Capacity            | Type                | Tank ID     | SE GPS                |       |
| PRODUCED WATER  | 1        | OTHER               | PBV STEEL           |             |                       |       |
| Comment: <a href="#">Shares containment with crude oil tanks.</a> |          |                     |                     |             |                       |       |
| Corrective Action:  |          |                     |                     |             |                       | Date: |
| <b>Paint</b>  |          |                     |                     |             |                       |       |
| Condition   | Adequate |                     |                     |             |                       |       |
| Other (Content)   |          |                     |                     |             |                       |       |
| Other (Capacity)  | 110 BBL  |                     |                     |             |                       |       |
| Other (Type)  |          |                     |                     |             |                       |       |
| <b>Berms</b>  |          |                     |                     |             |                       |       |
| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |       |
|   |          |                     |                     |             |                       |       |
| Comment:  |          |                     |                     |             |                       | Date: |
| Corrective Action:  |          |                     |                     |             |                       | Date: |
| Contents  | #        | Capacity            | Type                | Tank ID     | SE GPS                |       |
| CRUDE OIL   | 2        | 300 BBLs            | STEEL AST           |             | 40.312500,-104.488200 |       |
| Comment:  |          |                     |                     |             |                       |       |
| Corrective Action:  |          |                     |                     |             |                       | Date: |
| <b>Paint</b>  |          |                     |                     |             |                       |       |
| Condition   | Adequate |                     |                     |             |                       |       |
| Other (Content)   |          |                     |                     |             |                       |       |
| Other (Capacity)  |          |                     |                     |             |                       |       |
| Other (Type)  |          |                     |                     |             |                       |       |
| <b>Berms</b>  |          |                     |                     |             |                       |       |
| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |       |
|   |          |                     |                     |             |                       |       |

|                    |          |                 |                |          |       |
|--------------------|----------|-----------------|----------------|----------|-------|
| Earth              | Adequate | Walls Sufficent | Base Sufficent | Adequate |       |
| Comment:           |          |                 |                |          |       |
| Corrective Action: |          |                 |                |          | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 448118 Type: TANK API Number: - Status: AC Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p><b>COGCC Inspection Report Summary</b><br/>                     On Thursday 7/30/20 at approximately 0847hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Watkins 18-1 tank battery of Noble Energy at Facility ID: 448118 in Weld County, Colorado.<br/>                     While there, I observed a tank battery that is SI. See attached photo.<br/>                     No violation of the COGCC rules were observed at the time of inspection.<br/>                     This is a summary of inspection report.<br/>                     Continuing education inspections</p> | burnsa | 07/30/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 699102155    | Inspection Photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5214448">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5214448</a> |