

Inspection Photos
Location Name: McCallum Unit 112
Location ID: 324679

Click here to read the Form
State of Colorado
Oil and Gas Conservation Commission

MECHANICAL INTEGRITY TEST

Oil and Gas Operator Number: **1122**

Well Name: **PRREB**

Well ID: **1126-1150**

Well Type: **SMUT - IN PRODUCTION WELL** **INJECTION WELL**

Test Type: Test to Maintain SPTA Values 5 year UIC Annual UIC Test

Wellhead Data at Time of Test: **PRREB** 1126-1150

Casing Depth (Actual): **2,375'** Casing Depth (Design): **940'**

Tubing Casing/Annulus Test

Test Pressure (psi)	Flow Rate (gpm)	Test Duration (min)	Pressure Drop (psi)
500 ps.	0 ps.	0 min	0 ps.
800 ps.	0 ps.	0 min	0 ps.
200 ps.	0 ps.	0 min	0 ps.

Field Inspector: **Early Walker**

Signature: **Jeffrey Bowley**, Title: **Production Supervisor**, Date: **7-29-2020**

Signature: **[Signature]**, Title: **Field Inspector**, Date: **7/29/20**

Stamp: **2020 12:43**

Photo 1. Photo of Form 21 as filled out and signed in the field.