

Inspection Photos
Location Name: Upr Coan #1
Location ID: 320132



Photo #1 Tanks.



Photo #2 Separator and Meter



Inspection Photos
Location Name: Upr Coan #1
Location ID: 320132



Photo #3 Well Head.



Photo #4 open top produced water tank.



Inspection Photos
Location Name: Upr Coan #1
Location ID: 320132



Photo #5 hole on wildlife netting on produced water tank.



Photo #6 dead bird in produced water tank.

Inspection Photos
Location Name: Upr Coan #1
Location ID: 320132




Photo #7 dead birds in produced water tank.




Photo #8 dead birds in produced water tank.

Inspection Photos
Location Name: Upr Coan #1
Location ID: 320132



Photo #9 dead bird in produced water tank.



Photo #10 dead birds in produced water tank.

Inspection Photos
Location Name: Uprr Coan #1
Location ID: 320132



Photo #11 no bull plug in load off line.