

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2020

Submitted Date:

07/25/2020

Document Number:

688308262**FIELD INSPECTION FORM**

Loc ID 416953 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10706Name of Operator: D90 ENERGY LLCAddress: 202 TRAVIS STREET #402City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent
Vincent, Kenny	(337) 654-9404	kvincent@reagan.com	Principal Agent
Koehler, Bob		bob.koehler@state.co.us	
James, Cole	719-892-0378	cj0378@hotmail.com	Pumper
Quint, Craig		craig.quint@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416957	WELL	IJ	10/20/2017	DSPW	073-06413	JOHN CRAIG 7-2	SI

General Comment:Reinspection, UIC MIT, passed

Inspected FacilitiesFacility ID: 416957 Type: WELL API Number: 073-06413 Status: IJ Insp. Status: SI**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: CDHL

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 07/08/2019

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: Verification of Repairs Tbg psi: -11 Csg psi: 0 BH psi: Down toInsp. Status: Pass

Comment: Extreme Heat Truck MIRU
0 min 389 psi
5 min 385 psi
10 min 381 psi
15 min 381 psi
After test, casing 0 psi, tubing -11 psi (-11 throughout test), Brhd Down to 0 psi

Corrective Action: Operator to submit Form 21 to COGCC database within 10 days. Date: 08/07/2020**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI for test

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402452572	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5210501
688308263	D90 Energy John Craig 7-2 well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5210498
688308264	D90 Energy John Craig Extreme Heat truck	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5210499
688308266	Form 21	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5210500