

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/30/2020

Submitted Date:

08/01/2020

Document Number:

696103427

FIELD INSPECTION FORM

Loc ID 310499 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293203	WELL	PA	03/20/2017	OW	123-26498	FOSS 14-41	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Abandoned. ALL equipment removed.
Abandoned Battery SE corner GPS coordinates: 40.483658, -104.508038

Abandoned Centralized Battery formerly served 4 Location IDs (310499, 306251, 310500, 310501).
(Well(s): 4: Plugged & Abandoned | PA).

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type		#			corrective date
Gas Meter Run		# 0			
Comment:	Plugged & Abandoned PA. Battery Abandoned. ALL Equipment Removed.				
Corrective Action:					Date:
Plunger Lift		# 0			
Comment:	Plugged & Abandoned PA. Battery Abandoned. ALL Equipment Removed.				
Corrective Action:					Date:
Horizontal Heated Separator		# 0			
Comment:	Plugged & Abandoned PA. Battery Abandoned. ALL Equipment Removed.				
Corrective Action:					Date:
Emission Control Device		# 0			
Comment:	Plugged & Abandoned PA. Battery Abandoned. ALL Equipment Removed.				
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0					
Comment:	Plugged & Abandoned PA. Battery Abandoned. ALL Equipment Removed.					
Corrective Action:						Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	0				,		
Comment:		Plugged & Abandoned PA. Battery Abandoned. ALL Equipment Removed.					
Corrective Action:						Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No		
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 293203 Type: WELL API Number: 123-26498 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 07/30/2020 at approximately 12:17 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: FOSS-66N64W /14NESE Location ID: 310499 Well Name: Foss 14-41 API: 05-123-26498 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment removed. Abandoned Battery SE corner GPS coordinates: 40.483658, -104.508038</p> <p>Abandoned Centralized Battery formerly served 4 Location IDs (310499, 306251, 310500, 310501). (Well(s): 4: Plugged & Abandoned PA).</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Well appears to be cut / capped. Form 6 doc. #401221263 indicates plugging, cut/cap date: 01/24/2017. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	08/01/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103428	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215021