

Inspection Photos  
Location Name: PHINNEY-66N64W /10SWSE  
Location #: 305858



Photo #1

Phinney 34-10 (05-123-23589) Wellsite

Shut-In | SI

Weeds



Photo #2

Phinney 34-10 Wellsite

Shut-In | SI

Weeds: Mitigated

**Inspection Photos**  
**Location Name: PHINNEY-66N64W /10SWSE**  
**Location #: 305858**



**Photo #3**

**Phinney 44-10, 33-10, 34-10, 43-10** Battery site

**Inactive | Shut-down**

*prior insp.*