



39.71028, -108.88242, 7953.3ft, 156°
07/31/2020 03:21:11 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

USA 1

API: 05-103-05012

Inspection: 700402670



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Location.

USA 1

API: 05-103-05012

Inspection: 700402670



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Lease road entrance. Now hiking trail.

USA 1

API: 05-103-05012

Inspection: 700402670



39.70986, -108.88225, 7950.2ft, 29°
07/31/2020 03:23:07 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Well.

USA 1

API: 05-103-05012

Inspection: 700402670



39.70822, -108.87584, 7996.8ft, 315°
07/31/2020 03:11:26 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Photo 5. Cable located 200' from trail entrance
and 0.5 miles from well.**

USA 1

API: 05-103-05012

Inspection: 700402670



39.71005, -108.88234, 7955.1ft, 82°
07/31/2020 03:22:31 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Camp trash on location.

USA 1

API: 05-103-05012

Inspection: 700402670

