

BP L48 San Juan



V2 Compliance Follow Up Form

18149871802

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200728-18149871802

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Jul 28, 2020 11:24:46 AM MDT

91 S Skylane Dr, Durango, CO 81303, USA

Jul 28, 2020 11:27:39 AM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Jul 24, 2020

Well Name

HUNTINGTON GAS UNIT A 1

API Number

50670692100

Select State

Colorado

Work type

COGCC Inspection AR

Photo of first corrective action completed



Completed work description Corrective
Action 1

location sign

Photo of second corrective action completed



**Completed work description of corrective
action 2**

rills before seeding and blanket

Photo of third corrective action completed



**Completed work description of corrective
action 3**

view of rilling

Photo of fourth corrective action completed

**Completed work description**

seeded and blanketed slopes with 100% biodegradable blanket

Completed work description of corrective action 4

seeded and blanketed slopes

Additional photos**Additional photos**



Completed work description

seeded and blanketed slopes

Summary of all work completed

seeded and blanketed slopes that had erosion issues