

BP L48 San Juan



V2 Compliance Follow Up Form

18150259917

Reference Number:

20200731-18150259917

Form Name:

V2 Compliance Follow Up Form

Submitter Name:

Cole Nichols (colen@horizonenvservices.com) |
colen@horizonenvservices.com

Submission Date:

Jul 31, 2020 5:47:33 PM MDT

Location:

91 S Skylane Dr, Durango, CO 81303, USA

Jul 31, 2020 5:47:21 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Jul 31, 2020

Well Name

BUSH FEDERAL GAS UNIT 2

API Number

50670866300

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

weed removal

Photo of second corrective action completed



Completed work description of corrective action 2

weed removal

Photo of third corrective action completed



Completed work description of corrective action 3

weeds removed

Photo of fourth corrective action completed



Completed work description of corrective action 4

weed removal

Additional photos



Summary of all work completed

removed weeds