

BP L48 San Juan



V2 Compliance Follow Up Form

18150258941

Reference Number:

20200731-18150258941

Form Name:

V2 Compliance Follow Up Form

Submitter Name:

Cole Nichols (colen@horizonenvservices.com) |
colen@horizonenvservices.com

Submission Date:

Jul 31, 2020 5:53:01 PM MDT

Location:

91 S Skylane Dr, Durango, CO 81303, USA
Jul 31, 2020 5:52:46 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Jul 31, 2020

Well Name

BAIRD GAS UNIT A 2

API Number

50670970400

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

sign

Photo of second corrective action completed



Completed work description of corrective action 2

removed weed

Photo of third corrective action completed



Completed work description of corrective action 3

removed weed

Photo of fourth corrective action completed



Completed work description

removed weed

Completed work description of corrective action 4

removed weed

Additional photos



Summary of all work completed

removed weed