

Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #1 Location



Photo #2 Pits Signs

Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #3 Pit Signs

Photo #4 No Trash

Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #5 No Trash/ no unused equipment

Photo #6 No unused Equipment

Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #7 Well Location

Photo #8 No Unused Methanol Totes

Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #9 Placards

Photo #10 Placards

Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800




Photo #11 No Unused Equipment