

# Inspection Photos

7/28/2020

Operator: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release  
Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release



**Photo 1:** Photo taken from the eastern (upland) reclamation/remediation areas. Photo shows some germination evident, however Location is predominantly vegetated by undesirable weedy plant species, as well as noxious weeds such as Halogeton.



Inspection Photos  
Operator Name: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release



**Photo 2:** Photo shows soil surface on the remediation/reclamation area. Some germination evident, however it does not appear to be sufficient for reclamation to be considered “in process”.



Inspection Photos  
Operator Name: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release



**Photo 3:** Photo taken from the irrigation ditch. Photo shows tamarisk establishing in ditch. This is a Colorado State listed noxious weed.





Inspection Photos  
Operator Name: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release



**Photo 4:** Photo taken from slope below ditch. Photo shows some germination, however vegetation is predominantly weedy plant species.



Inspection Photos  
Operator Name: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release



**Photo 5:** Photo taken from the areas of the reclamation where surface owner is irrigating; Vegetation observed is predominantly undesirable weedy plant species.



Inspection Photos  
Operator Name: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release



**Photo 6:** Continued from photo 5. Photo also shows reclamation area is predominantly undesirable weedy plant species. Photo also show Field Bindweed establishment on the reclamation area. This is a Colorado State listed noxious weed.



**Inspection Photos**  
**Operator Name: BARGATH LLC - 10128**  
**Facility ID: 460855 - Spill/Release**



**Photo 7:** See comments under photo 6.





**Inspection Photos**  
**Operator Name: BARGATH LLC - 10128**  
**Facility ID: 460855 - Spill/Release**



**Photo 8:** See comments under photo 6.



Inspection Photos  
Operator Name: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release



**Photo 9:** Photo taken from the lower/western reclamation areas, facing north. Though desirable perennial vegetative germination is more prevalent, areas remain predominantly weedy plant species.



**Inspection Photos**  
**Operator Name: BARGATH LLC - 10128**  
**Facility ID: 460855 - Spill/Release**



**Photo 10:** See comments under photo 9.



Inspection Photos  
Operator Name: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release



**Photo 11:** Photo of Chicory observed throughout the Location. This is a Colorado State listed noxious weed.



Inspection Photos  
Operator Name: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release



**Photo 12:** Photo taken from riparian areas on the western end of the reclamation area. Reclamation appears be progressing in these areas.





Inspection Photos  
Operator Name: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release



**Photo 13:** Photo taken from the riparian disturbance. Photo shows Bull thistle establishment. This is a Colorado State listed noxious weed.



Inspection Photos  
Operator Name: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release



**Photo 14:** Photo taken from the riparian disturbance. Photo shows Musk thistle establishment. This is a Colorado State listed noxious weed.



Inspection Photos  
Operator Name: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release



**Photo 15:** Photo taken from the riparian disturbance. Photo shows Canada thistle (rosettes) as well as Chicory establishment. This is a Colorado State listed noxious weed.



Inspection Photos  
Operator Name: BARGATH LLC - 10128  
Facility ID: 460855 - Spill/Release



**Photo 16:** Photo of the adjacent reference area for comparison.