

Inspection Photos
Location Name: Marick 1061-6-41
Location ID: 410175



Photo 1 – Pumping Unit



Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Marick 1061-6-41
Location ID: 410175



Photo 3 – Tank Battery, weeds



Photo 4 – Heater Treater, weeds



Inspection Photos
Location Name: Marick 1061-6-41
Location ID: 410175



Photo 5 – Tank Battery Sign – Legal’s not accurate; Well is in T10N not T11N



Photo 6 – Produced Water Tank missing Capacity Label