

BP L48 San Juan



V2 Compliance Follow Up Form

18150414745

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200803-18150414745

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Aug 3, 2020 12:42:34 PM MDT

91 S Skylane Dr, Durango, CO 81303, USA

Aug 3, 2020 12:41:18 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Jul 30, 2020

Well Name

MCCOY, ROBERT GAS UNIT B 3

API Number

50670963500

Select State

Colorado


Work type

COGCC Inspection AR

Action Complete

Clean Up Weed Debris


Photo of first corrective action completed



**Completed work description Corrective
Action 1**

removed weeds


Photo of second corrective action completed



**Completed work description of corrective
action 2**

removed weeds

Photo of third corrective action completed



**Completed work description of corrective
action 3**

removed weed


Photo of fourth corrective action completed




**Completed work description of corrective
action 4**

removed weed

Additional photos



Additional photos

**Summary of all work completed**

removed weeds. most weeds were treated and dead. did remove a few live weeds. walked full reclaimed area.