

BP L48 San Juan



V2 Compliance Follow Up Form

18150416266

Reference Number:

20200803-18150416266

Form Name:

V2 Compliance Follow Up Form

Submitter Name:

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Submission Date:

Aug 3, 2020 12:53:05 PM MDT

Location:

1916-1922 N La Boca Canyon Rd, Ignacio, CO 81137, USA

Aug 3, 2020 12:52:56 PM MDT [[View Map](#)]

INFORMATION

Section 1

| | |
|------------------------|--|
| Name | kenneth.canterbury@crossfire-llc.com |
| Well Name | KNIGHT GAS UNIT 1 MV |
| API Number | 50670507600 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Repaired Berm |

Photo of first corrective action completed



Completed work description Corrective Action 1

Compliance

Photo of second corrective action completed



Completed work description of corrective action 2

Installed rock run down

Photo of third corrective action completed



Completed work description of corrective action 3

Fixed erosion

Photo of fourth corrective action completed



Completed work description

Fixed berm around pit

Completed work description of corrective action 4

Picked up trash

Additional photos



Summary of all work completed

Compliance, cleaned up trash , fixed berm , installed rock run down marked anchors and fixed erosion