

Inspection Photos

Location Name: LARAMIE ENERGY LLC Gipp /18-12 Pad

Location ID: 334501



Photo #1660 from entrance to location



Photo #1661 Gipp 18-14 wellhead leaking at the casing pressure transducer.