

# Interim Reclamation and Stormwater Inspection

July 30, 2020

Operator: PAINTED PEGASUS PETROLEUM LLC - #10711

Location ID: 320082

Inspection Document #: 697501823

Adams County, CO

NENE Section 8 T1S R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: WANDA #41-8  
Location ID: 320082



**Photo 1.** Photo taken from the Wanda well location, facing East. Photo illustrates the Operator sign.



Inspection Photos  
Location Name: WANDA #41-8  
Location ID: 320082



**Photo 2.** Photo taken from the Wanda well location, facing East. Photo illustrates there are no reclamation compliance issues observed at the time of this inspection.



Inspection Photos  
Location Name: WANDA #41-8  
Location ID: 320082



**Photo 3.** Photo taken from the tank battery, facing West. Photo illustrates Operator signs and which wells the tank battery services.



Inspection Photos  
Location Name: WANDA #41-8  
Location ID: 320082



**Photo 4.** Photo taken from the northern tank battery, facing South. Photo illustrates unmanaged weeds.



Inspection Photos  
Location Name: WANDA #41-8  
Location ID: 320082



**Photo 5.** Photo taken from the central tank battery, facing South. See comments under Photo 3.



Inspection Photos  
Location Name: WANDA #41-8  
Location ID: 320082



**Photo 6.** Photo taken from the southwestern tank battery, facing North. See comments under Photo 3.



Inspection Photos  
Location Name: WANDA #41-8  
Location ID: 320082



**Photo 7.** Photo taken from the southeastern tank battery, facing West. Photo illustrates weed debris mixed with piled gravel from previous weed management; appears the Operator used a skid-steer to pile up weed debris/gravel. Surface owner can no longer drive mower through this section of land.

