

# Interim Reclamation and Stormwater Inspection

July 30, 2020

Operator: PAINTED PEGASUS PETROLEUM LLC - #10711

Location ID: 320137

Inspection Document #: 697501825

Adams County, CO

NWNE Section 17 T1S R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: UPPR-JULIE #1  
Location ID: 320137



**Photo 1.** Photo taken from the tank battery. Photo illustrates Operator sign and which well the tank battery services.



Inspection Photos  
Location Name: UPPR-JULIE #1  
Location ID: 320137



**Photo 2.** Photo taken from the tank battery, facing Southeast. Photo illustrates unmanaged weeds.



Inspection Photos  
Location Name: UPPR-JULIE #1  
Location ID: 320137



**Photo 3.** Photo taken from the tank battery, facing West. See comments under Photo 2.



Inspection Photos  
Location Name: UPPR-JULIE #1  
Location ID: 320137



**Photo 4.** Photo taken from the tank battery, facing East. See comments under Photo 2.



Inspection Photos  
Location Name: UPPR-JULIE #1  
Location ID: 320137



**Photo 5.** Photo taken from the tank battery, facing South. See comments under Photo 2.



Inspection Photos  
Location Name: UPPR-JULIE #1  
Location ID: 320137



**Photo 6.** Photo taken from the tank battery, facing South. Photo illustrates weeds around the well location.

