

Interim Reclamation and Stormwater Inspection

July 30, 2020

Operator: PAINTED PEGASUS PETROLEUM LLC - #10711

Location ID: 319664

Inspection Document #: 697501827

Adams County, CO

NENE Section 10 T1S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RANDALL #41-10
Location ID: 319664



Photo 1. Photo taken from the tank battery. Photo illustrates Operator sign and which well the tank battery services.



Inspection Photos
Location Name: RANDALL #41-10
Location ID: 319664



Photo 2. Photo taken from the tank battery, facing Southeast. Photo illustrates unmanaged weeds.



Inspection Photos
Location Name: RANDALL #41-10
Location ID: 319664



Photo 3. Photo taken from the tank battery, facing East. See comments under Photo 2.



Inspection Photos
Location Name: RANDALL #41-10
Location ID: 319664



Photo 4. Photo taken from the eastern tank battery, facing East. See comments under Photo 2.



Inspection Photos
Location Name: RANDALL #41-10
Location ID: 319664



Photo 5. Photo taken from the eastern tank battery, facing North. See comments under Photo 2.

