

Interim Reclamation and Stormwater Inspection

July 30, 2020

Operator: PAINTED PEGASUS PETROLEUM LLC - #10711

Location ID: 320049

Inspection Document #: 697501829

Adams County, CO

NENW Section 12 T1S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SHIVELY #21-12
Location ID: 320049



Photo 1. Photo taken from the tank battery. Photo illustrates Operator sign and which well the tank battery services. Note the Operator sign is in need of repair



Inspection Photos
Location Name: SHIVELY #21-12
Location ID: 320049



Photo 2. Photo taken from the tank battery, facing South. Photo illustrates unmanaged weeds.



Inspection Photos
Location Name: SHIVELY #21-12
Location ID: 320049



Photo 3. Photo taken from the tank battery, facing South. See comments under Photo 2.



Inspection Photos
Location Name: SHIVELY #21-12
Location ID: 320049



Photo 4. Photo taken from the eastern tank battery, facing South. See comments under Photo 2.

