

# Interim Reclamation and Stormwater Inspection

July 30, 2020

Operator: PAINTED PEGASUS PETROLEUM LLC - #10711

Location ID: 320027

Inspection Document #: 697501831

Adams County, CO

SWNE Section 12 T1S R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: GEORGENE #32-12  
Location ID: 320027



**Photo 1.** Photo taken from the tank battery. Photo illustrates Operator sign and which well the tank battery services. Note the Operator sign is in need of repair



Inspection Photos  
Location Name: GEORGENE #32-12  
Location ID: 320027



**Photo 2.** Photo taken from the tank battery, facing South. Photo illustrates unmanaged weeds.



Inspection Photos  
Location Name: GEORGENE #32-12  
Location ID: 320027



**Photo 3.** Photo taken from the tank battery, facing East. See comments under Photo 2.

