

Interim Reclamation and Stormwater Inspection

July 30, 2020

Operator: SMITH OIL PROPERTIES INC - #79905

Location ID: 320195

Inspection Document #: 697501833

Adams County, CO

SENE Section 8 T1S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LAURIDSON #42-8
Location ID: 320195



Photo 1. Photo taken from the tank battery. Photo illustrates Operator sign and which well the tank battery services.

Inspection Photos
Location Name: LAURIDSON #42-8
Location ID: 320195



Photo 2. Photo taken from the tank battery, facing North. Photo illustrates unmanaged weeds.



Inspection Photos
Location Name: LAURIDSON #42-8
Location ID: 320195



Photo 3. Photo taken from the tank battery, facing West. See comments under Photo 2.

Inspection Photos
Location Name: LAURIDSON #42-8
Location ID: 320195



Photo 4. Photo taken from the tank battery, facing South. See comments under Photo 2.



Inspection Photos
Location Name: LAURIDSON #42-8
Location ID: 320195



Photo 5. Photo taken from the well location, facing West. Photo illustrates there was no observed reclamation compliance issues.

