

Inspection Photos

Location Name: Kobe-Chevron Valve Can

Spill/Release ID: #468517, Remediation Project #14368

Inspection Date: August 4, 2020




Photo #1 – Valves attached to flowline riser neither locked nor tagged out.



Photo #2 - View of valve can area, looking west.



Inspection Photos

Location Name: Kobe-Chevron Valve Can

Spill/Release ID: #468517, Remediation Project #14368

Inspection Date: August 4, 2020



Photo #3 – View of stormwater ditch on south side of S. Dry Fork Rd, looking east.



Photo #4 – View of turn-out parking area on south side of S. Dry Fork Rd, looking southeast.



Inspection Photos

Location Name: Kobe-Chevron Valve Can

Spill/Release ID: #468517, Remediation Project #14368

Inspection Date: August 4, 2020



Photo #5 – Wooden stakes remaining at former hay bale installation in drainage north of S. Dry Fork Rd.



Photo #6 – Vegetation growth and flowing water in natural drainage located approximately 1000' east of valve can.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources