

**Inspection Photos**  
**Location Name: Albert Sack D1**  
**Location ID: 320001**



**Pic 1 weeds on location**



**Pic 2 weeds on location**

**Inspection Photos**  
**Location Name: Albert Sack D1**  
**Location ID: 320001**



**Pic 3 Unable to check calibration of gas meter run due to  
hornet nest inside/weeds around gas meter run**