

Inspection Photos

API: 071-07204

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 8/3/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07204 | Date: 8/3/2020

Inspection Photos



Photo 1. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07204 | Date: 8/3/2020

Inspection Photos



Photo 2. Facing southeast at the location. This area of the location appears to have been stabilized and the fill slope is resloped.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07204 | Date: 8/3/2020

Inspection Photos



Photo 3. Facing down toward the fill slope. This area which had sloughed off has been resloped and temporarily stabilized with straw blanket.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07204 | Date: 8/3/2020

Inspection Photos



Photo 4. Facing southeast along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07204 | Date: 8/3/2020

Inspection Photos



Photo 5. Southeast corner facing toward the location. It appears work is still in progress installing straw blanket.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07204 | Date: 8/3/2020

Inspection Photos



Photo 6. Facing toward the location from across the canyon.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07204 | Date: 8/3/2020