

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/04/2020

Submitted Date:

08/04/2020

Document Number:

700701265

FIELD INSPECTION FORMLoc ID 334855 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------------------|---------|
| , Caerus | | COGCC.inspections@caerus oilandgas.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 211282 | WELL | SI | 09/01/2019 | GW | 045-07041 | DUNN 4-16 | SI |
| 267800 | WELL | PR | 08/01/2019 | GW | 045-09216 | DUNN 4-16B (P4E) | PR |
| 267802 | WELL | SI | 09/01/2019 | GW | 045-09214 | HILL 10-4B(R4E) | SI |
| 272467 | WELL | PR | 09/18/2004 | GW | 045-10086 | DUNN 3-13B (P4E) | PR |
| 272469 | WELL | PR | 09/12/2004 | GW | 045-10087 | DUNN 3-13C (P4E) | PR |

General Comment:**COGCC Inspection Report Summary**

On Tuesday 8/4/20 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus O4E, at Location # 323976 in Garfield county Colorado.

While there, I observed normal production operations. Three of the five meters have been calibrated on location within the past year. Two wells are shut in and were last calibrated 4/17/2019, last production on these wells was 8/1/2019.

This is a summary of inspection report.

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|-----|-------|--|
| Comment: | 911 | | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|--------|-------|--|
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------|-----|--|-----------------|
| Type: Bird Protectors | # 5 | | corrective date |
| Comment: | | | |

| | | | |
|-----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|--|
| Corrective Action: | | Date: | |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 2 | | |
| Comment: | API # 045-07041 and 045-09214 wells are shut in and were last calibrated 4/17/2019, last production on these wells was 8/1/2019. Wells have not been calibrated in the past year. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 2 | | |
| Comment: | well heads | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------------------|---------|--------|
| CONDENSATE | 2 | 300 BBLS | HEATED STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------|----|--|
| Yes/No | NO | |
|--------|----|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 211282 Type: WELL API Number: 045-07041 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: last produced from data base is 8/1/2019

Corrective Action: _____ Date: _____

Facility ID: 267800 Type: WELL API Number: 045-09216 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action: _____ Date: _____

Facility ID: 267802 Type: WELL API Number: 045-09214 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: last produced from data base is 8/1/2019

Corrective Action: _____ Date: _____

Facility ID: 272467 Type: WELL API Number: 045-10086 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action: _____ Date: _____

Facility ID: 272469 Type: WELL API Number: 045-10087 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Gravel | | | | |
| Ditches | | Ditches | | | | |
| Berms | | Culverts | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 700701273 | Photos for P4E | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5216987 |